

Information regarding All Series 10 (MSN 401-888) aircraft.

A Service bulletin has been issued regarding potential problems with the Overhead Control Panel. See attached Service Bulletin.

You should check with your Service Center regarding the recommended repair.

What also needs to be known is the cost of replacing the Overhead Control Panel if a problem involving one of the noted items from the Service Bulletin occurs prior to having this SB completed? IF one of the suspect switches fails it requires the replacement of the Overhead Control Panel-not just the offending switch. Cost is \$5500.00 *and* you still will need to have this SB done (approximately 40 hours of labor).

